

Fort Johnson and Fort Hunter Locks & Overpass

The grid work was in the process of being painted, this is why the beige covering on the grid work. The powerful force of the water swept all the equipment including trucks and trailers. The flood gates in the lower photo show the river water level control badly bent and though you can't see it, the lock gates were also blown out.





08/30/2011